

# Ontario Mine Rescue Heat Exposure Standard

<b>W e t  B u l b  T e m p.</b>	<b>38</b>								19	19	19	19	0	0	0	
	<b>37</b>								20	19	19	19	19	19	0	
	<b>36</b>							22	22	21	20	20	19	19	19	
	<b>35</b>							24	23	22	22	22	21	20	20	
	<b>34</b>						27	26	25	24	23	23	22	22	22	
	<b>33</b>						29	28	27	27	26	25	24	23	23	
	<b>32</b>					33	32	31	30	29	28	27	26	26	25	
	<b>31</b>					38	36	35	33	32	31	30	29	28	27	
	<b>30</b>				46	44	42	40	38	36	34	33	32	30	30	
	<b>29</b>				53	50	48	45	43	41	39	38	36	34	32	
	<b>28</b>			63	60	57	55	52	50	47	45	43	41	39	37	
	<b>27</b>			72	69	66	63	60	57	54	52	49	47	45	43	
	<b>26</b>		87	83	79	75	72	68	65	62	59	56	54	51	49	
	<b>25</b>		99	95	90	86	82	78	75	71	68	65	62	59	56	
	<b>24</b>	119	114	108	103	99	94	90	85	81	78	74	71	67	64	
	<b>23</b>	*	*	*	118	113	108	103	98	93	89	85	81	77	73	
		<b>24</b>	<b>26</b>	<b>28</b>	<b>30</b>	<b>32</b>	<b>34</b>	<b>36</b>	<b>38</b>	<b>40</b>	<b>42</b>	<b>44</b>	<b>46</b>	<b>48</b>	<b>50</b>	
	<b>Dry Bulb Temp.</b>															

Cross referencing the Wet Bulb and Dry Bulb temperatures indicates the maximum time exposure in minutes.  
 Exposure limits include time for entry, exit, and rest breaks.  
 Exposure limits must not be exceeded.

